

Fig. 1




Fig. 2




Fig. 3

662180" 6/04/86

ECC Errors Detected by Drive Electronics and Corrected By Device Driver in Host

662780 1/04/2000

